## Delaware Department of Transportation Division of Transportation Solutions Design Guidance Memorandum

Memor	randum Number 2-5			
<ol> <li>Road Design Manual</li> <li>Bridge Design Manual</li> <li>Utilities Design Manual</li> <li>Real Estate Manual</li> <li>Standard Specifications</li> <li>Standard Construction Details</li> </ol>				
Title: Section Re	ns to Implement: _ Road, _	X Bridge, X PMT, Design Support, S agement, X Field Services, X District.	Effective date: June 1, 2002 pecification, Utility, Other	
I.	Purpose:			
	To provide guidance on proper scupper design for preventing siltation and debris build-up when the use of scuppers is necessary.			
II.	Design Guidance:			
	<ol> <li>Scuppers should be designed with proper inlet opening to minimize clogging from siltation or debris.</li> </ol>			
	<ol> <li>The installation of a drainage inlet upslope of the bridge can minimize the need of bridge deck scuppers and the clogging problem.</li> <li>The downslope drainage inlet beyond the bridge should be designed assuming 50% of bridge deck scuppers are clogged.</li> <li>The scuppers should be located at the desirable 2% minimum slope, both transversely and longitudinally, to achieve self-cleansing velocity.</li> <li>The minimum height of a curb or parapet opening should be 4 inches. This consists of 3" curb opening and 1" deck depression with proper transition. The bottom side of the opening should be adequately sloped.</li> </ol>			
	FH' 2. Bri	<ol> <li>Design of Bridge Deck Drainage, Hydraulic Engineering circular No. 21, FHWA May 1993.</li> <li>Bridge Deck Drainage Guidelines, FHWA December 1986.</li> <li>Bridge Design Manual, Chapter 3.</li> </ol>		
III.	Justification:			
	Clogged scuppers are a widespread maintenance problem and they can add to a safety problem due to ponding or icing.			
	Prepared and	/S/ Chao H. Hu	May 20, 2002	
	Recommended by:	Assistant Chief Engineer	Date	
	Approved:	/S/ Carolann D. Wicks Director of Transportation Solutions	May 29, 2002 Date	
	Distribution: Transportation Solutions Section Heads			

District Engineers Consultants